

Material Testing and Non-Destructive Testing

**Contact:**  
**E-Z Lok Division**  
240 E. Rosecrans Avenue  
  
Gardena, CA 90248

15062 Bolsa Chica  
Huntington Beach, CA 92649  
USA

Telephone : (714) 892-1961  
Telefax : (714) 892-8159  
Website : www.storksmti.com

**Date:** 2/15/2005    **P.O. No.:** ES-1840    **W/O No.:** EZL001-01-21-55796-4

**TEST CERTIFICATE**

<b>Part No.:</b>	329-3
<b>Internal Thread:</b>	10-24
<b>Material:</b>	12L14
<b>Description:</b>	Insert
<b>Test Plate Material:</b>	2024-T4 Aluminum

**PULL TEST**

**Specifications:** NO SPECIFICATION  
**Requirement:** N/S  
**Test Method:** MIL-STD-1312-8A/NASM 1312-8

<b>Sample</b>	<b>Result (lbs.)</b>	<b>Location of Fracture</b>
329-3	3,517	MANDREL
329-3	3,529	MANDREL
329-3	3,366	MANDREL

**FOR INFORMATION ONLY**



NDT AND  
MATERIALS TESTING  
FASTENER TESTING



CHEMICAL  
MECHANICAL  
FASTENERS

Respectfully submitted

*Elaine Scott*  
Elaine Scott  
Senior Quality Administrator

The information contained in this certification represents only the material submitted and is certified only for the quantities tested. Reproduction except in full is reserved pending written approval. All testing was performed in a mercury-free environment. A2LA accreditation No. 0093-01 and 0093-02.

**Stork Materials Testing and Inspection is an operating unit of Stork materials Technology B.V., Amsterdam, The Netherlands, which is a member of the Stork group**